Maruti Baleno 2015-2022 1.2 Delta

Private



Jaipur (first) Rto, Rajasthan RTO	RJ14****** Registration number
01-09-2017 Manufacturing Date	12-10-2017 Registration Date
1 No. of Owners	75791 Odometer Reading #
Petrol Fuel Type	Manual Transmission
Prme. Ray Blue Color	

XXXXXXXXX Engine Number	XXXXXXXXXXXXXXXXX Chassis Number	Comprehensive Insurance Type	10-10-2023 Insurance Validity
Yes but not mentioned on RC Hypothecation	Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Fitment Endorsement RC	SBI Name of financer
Not Applicable CNG LPG Category	NA CNG Validity Date	Not Applicable CNG LPG Removal	0 Dedupe Count
- Dedupe Duration	Physical Inspection Inspection Type		

Summary

Overall Score 7 /10

- Car with ABS system
- Colourless exhaust emission
- Central Locking System
- Auto climate AC
- Excellent battery Performance
- Tyres in good condition

Body and Frame	8.5 /10	Exterior Details	3 /10
Interior Details	6 /10	Engine and Transmission	6 /10
Electricals	10 /10	Light	6.5 /10
Tyre	5.5 /10	Other Details	8.5 /10
Charger Details	0 /10		

Excellent | Good | Average | Poor

Use your smart phone to scan the QR code and get detailed inspection report

Download Video of Engine Noise

Remarks

Download images

Body and Frame 8.5 /10

- ✓ A pillar Left : Good
- ✓ A pillar Right : Good
- ✗ Quarter Panel Left : Dented > 10SqCm, Scratched 5Cm
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✗ Running Board Left : Scratched
- ✓ Dickey Floor and Back end Panel : Good
- ✓ B pillar Left : Good
- ✓ B pillar Right : Good
- ✗ Quarter Panel Right : Scratched (>5Cm)
- ✓ Apron Left : Good
- ✗ Running Board Right : Scratched
- ✓ Front Member (Bonnet Patti) : Good
- ✓ C pillar Left : Good
- ✓ C pillar Right : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Apron Right : Good
- ✓ Running Board Robotic Punches Original : Yes

Exterior Details 3 /10

- ✗ Front Bumper : Scratched, Replaced
- ✗ Fender Left : Dented (>10SqCm), Scratched (>5Cm)
- ✗ Rear Door Right : Dented (10SqCm), Scratched (>5Cm)
- ✗ Dicky/ Boot Door : Scratched (>5Cm)
- ✗ Rear Windshield : Spotted, Scratched
- ✓ Cowl top : Good
- ✓ Lamp support : Good
- ✗ Bonnet Quality : Repainted, Repaired, Scratched (5Cm)
- ✗ Fender Right : Repainted, Scratched (>5Cm)
- ✗ Rear Door Left : Dented (10SqCm), Dented (>10SqCm), Scratched (5Cm), Scratched (>5Cm)
- ✗ Roof Quality : Dented (10SqCm), Scratched (5Cm)
- ✗ ORVM Right Manual : Scratched
- ✓ Firewall : Good
- ✗ Side member : Rusted
- ✗ Front Windshield : Spotted
- ✗ Front Door Right : Scratched (>5Cm)
- ✗ Front Door Left : Dented (10SqCm), Scratched (>5Cm)
- ✗ Rear Bumper : Dented, Scratched
- ✓ ORVM Left Manual : Working
- ✓ Lower Member : Good

Interior Details 6 /10

- ✓ AC Cooling : Satisfactory
- ✗ Dash Board/Glove box : Scratched
- ✓ Floor carpet : Good
- ✓ Heater : Working
- ✗ Seat Cover : Torn
- ✓ Auto Climate AC : Working
- ✓ Music system : Working
- ✓ Roof carpet : Good

Engine and Transmission 6 /10

- ✓ Engine Mountings/Structure : Good
- ✗ Coolant : Dirty
- ✓ Smoke Colour/ Exhaust Emission : Colourless
- ✗ Blowby/Back compression : Oil Spillage on Idle
- ✓ Engine Sound/ Engine Noise : Normal
- ✓ Radiator : Good
- ✓ Gear Shifting mechanism performance : Smooth
- ✓ Manifold Catalytic Converter/ Silencer Mitti : Available
- ✗ Engine Oil : Dirty
- ✓ Radiator Fan : Working
- ✓ Blower Motor Noise : Normal

Electricals 10 /10

- ✓ Power Window Front Left : Working
- ✓ Alternator : Working
- ✓ Central Locking : Working
- ✓ Power Window Rear Left : Working
- ✓ Malfunction indicator light : Off
- ✓ Steering mounted Audio control : Working
- ✓ Self Starter Motor : Satisfactory
- ✓ Rear parking sensor : Working

Light 6.5 /10

- ✗ Head Light Left : Scratched
- ✗ Head Light Right : Scratched
- ✓ Tail Light Right : Good
- ✗ Tail Light Left : Damaged

Tyre 5.5 /10

- ✓ Right Front Tyre tread depth : 50-75%
- ✓ Right Rear Tyre tread depth : 50-75%
- ✓ Front Left Tyre tread depth : 50-75%
- ✓ Rear Left Tyre tread depth : 50-75%
- ✗ Spare tyre Available : Not Available
- ✗ Alloy wheels : No

Other Details 8.5 /10

- ✓ ABS : Available
- ✓ No. of airbags : 2
- ✓ Battery Performance : Satisfactory
- ✓ Steering operation : Smooth
- ✓ Brake effectiveness : Satisfactory
- ✓ Immobilizer : Available
- ✓ Clutch operation : Satisfactory
- ✗ Toolkit and jack : Both not available
- ✓ Front and rear axle performance : Smooth
- ✗ Suspension Noise : Noisy

Charger Details 0 /10

- ✗ Charger Type :



Profile Picture View



Right fender View



Right fender View



Right Side - Front Edge View



Right Side (fender, doors, qtr Panel) View




Right Side (fender, doors, qtr Panel) View



Right Side-Rear Edge View



Right Quarter Panel View



Rear Side- Right Edge View



Rear (bumper, dicky door, rr-windshield, tail lights) View



Rear Side- Left Edge View



Left Quarter Panel View



Left Side-Rear Edge View



Left Side (fender, doors, qtr Panel) View



Left Side (fender, doors, qtr Panel) View



Left Side-Front Edge View



Left Fender View



Left Side Profile Pic View



Front View (bumper, bonnet, fr-windshield,headlights, grill) View



Front Windscreen View




Front Windscreen View



Other Images View



Ac Cooling image View



Ac Cooling image View



Front Right or Left Side Interior View View



Front Right or Left Side Interior View View



Front Door Trim View



Rear Right or Left Side Interior View View



Rear Right or Left Side Interior View View



Dashboard (from rear seat) View



Dashboard (from rear seat) View



Gear Shift Lever (from rear seat) View




Odometer reading (with engine on from driver seat) View



Odometer reading (with engine on from driver seat) View



ABC Pedals (from driver seat) View




Front Right Tyre View



Front Right Tyre View



Rear Right Tyre View



Rear Right Tyre View



Rear Right Tyre View



Boot / Dicky View




Boot / Dicky View



Spare Tyre View



Spare Tyre View



Rear Left Tyre View



Rear Left Tyre View



Front Left Tyre View



Front Left Tyre View



Engine Compartment View

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (04/04/2023) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.
Note: To check the genuinity of condition report please scan the QR code on 1st page of report.
The odometer reading is at the time of inspection of car, actual odometer reading might vary